

# CORNER RECORD

Agency Index CR-22-033


Document Number \_\_\_\_\_

City of Stockton County of San Joaquin, California

Brief Legal Description Found monument as noted, referenced and left as found.

### CORNER TYPE

### COORDINATES (Optional)



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units  Metric  U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

Date of Survey September 12, 2020

PLS Act Ref.:  8765(d)  8771  8773  Other:

Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction

Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found a 3/4" Iron Pin, no tag, in monument well at the intersection of Miner Ave and California St. Set four (4) reference points, as noted on the reverse, outside of the construction limits.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on January 31, 2022

Signed James N. Landrum P.L.S. or R.C.E. No. 5837



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 1, 2022

and examined and filed February 14, 2022

Signed James E. Hart P.L.S. or R.C.E. No. 8657  
Title County Surveyor



County Surveyor's Comment

LEGEND:

- FOUND 3/4" IRON PIN IN MONUMENT WELL.
- SET REFERENCE POINT, CUT CROSS IN CONCRETE WALK, UNLESS OTHERWISE NOTED.

