


CORNER RECORD

Agency Index

CR-26-207

Document Number

City of _____ County of SAN JOAQUIN, CaliforniaBrief Legal Description POST-CONSTRUCTION TIES FOR MONUMENT PRESERVATION**CORNER TYPE****COORDINATES (Optional)**

- ☐ Government Corner ☒ Control
☐ Meander ☐ Property
☐ Rancho ☐ Other

Date of Survey March 20, 2026

N. _____ E. _____

Elevation _____

Units ☐ Metric ☐ U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902

PLS Act Ref.:

☐ 8765(d)☐ 8771☐ 8773☒ Other:Corner/
Monument:☐ Left as found☐ Established☐ Rebuilt☐ Pre-Construction☐ Found and tagged☐ Reestablished☐ Referenced☒ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet #2 for description(s):

POST-CONSTRUCTION TIES FOR MONUMENT PRESERVATION ON FARMINGTON ROAD, STATE
ROUTE 4, NEAR INTERSECTION WITH WALKER LANE

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on March 20, 2026

Signed

Carl L. Betz

P.L.S.

[REDACTED]

5650

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received

June 1, 2026

and examined and filed

June 12, 2026

Signed

Robert L. Borsdorf III

P.L.S. or R.C.E. No.

9728

Title

County Surveyor

County Surveyor's Comment



